







Feature

- -The hexagonal honeycomb shape is beautiful and stylish, and it is also very stable:
- -The lamp body is made of iron art high-temperature baking paint technology, which is fine and delicate, anticorrosive and antirust, stable in its color, durable and strong;
- -Lens light source, balanced illumination, clear and bright, long-lasting and high-brightness, and non-irritating;
- -Constant current LED drive power, no flicker, high stability, low energy consumption, more power saving;
- -Various application scenarios including department stores, supermarkets, indoor offices, fitness places, Internet cafes, corridors and aisles.

Luminaire parameters

Model	HL-H9870-L06	HL-H9856-L12	
Size	L600*W520*H70mm	L1200*W1039*H56mm	
Nominal Power	60W	90W	
Lm	3000lm	4300lm	
Beam Angle	110°		
Input Voltage	AC200-240V		
CCT	2700-6500k		
CRI	>80		
Protection Grade	IP40		
Certification	CE, ROSH		
Warranty	3 years		






Installation



Step 1: Use an electric drill tool to drill holes in the appropriate position on the wooden board or cement wall




Step 2: Fix the rubber plug on the hole in the wood or cement wall



Step 3: After installing the suspension wire adjuster into the suspension wire adjuster, use nuts to secure it to the ceiling plate




Step 4: Use screws to fix the ceiling cup on the wood or concrete wall



Step 5: After the lamp is installed on the sling, the installation is complete

Packing



Model	Carton box	QTY/Carton	
HL-H9870-L06	L610*W100*H535MM	1 PCS	
HL-H9856-L12	L1220*W80*H1070MM	1 PCS	

Notices

- 1. The power supply must be turned off before installation.
- 2. Make sure the product is mounted under the surface of the object to be installed, and finally turn on the power to light up.
- 3. This product is for indoor use only.
- 4. This product is warranted for 3 years and problems occur within 3 years (except for human factors and accidental factors), free maintenance.
- 5.The product is not responsible for damage caused by accidental factors or improper use.